UNITED STATES DISTRICT COURT SOUTHERN DISTRICT OF OHIO

08 MAY 14 AM 9: 07

UNITED STATES OF AMERICA, et al.,

CASE NO. C-1-02-107

Plaintiffs,

JUDGE S. ARTHUR SPIEGEL

MAGISTRATE HOGAN

-VS-

BOARD OF HAMILTON COUNTY COMMISSIONERS, et al.,

REQUEST FOR REVIEW

Defendants.

, request that the Court review my Water-in-

Basement claim, pursuant to the Court's February 2, 2006, Order. Attached hereto is the information detailing the nature of my dispute.

Date

S:\LRF\WIB\Pro se\Request For Review 112106.doc

Declarations

POLICY NUMBER 71.938525-50

EFFECTIVE DATE 05/08/07

ISSUE

01 (05/18/07)



STANDARD TIER

PAGE 1

NAMED INSURED

VICTORIA PATMAN 1252 ROSS AVE CINCINNATI OH 45205-1356 This Declarations together with the forms listed in the Schedule of Forms and Endorsements complete the above numbered policy.

POLICY PERIOD

From 05/08/07

to

05/08/08

This policy period begins and ends at 12:01 A.M. Standard Time at the residence premises as stated in the policy.

Insured Residence Premises	Description of Dwelling
1252 ROSS AVE CINCINNATI OH 45205	Year Built 1945 Construction MASONRY
County: HAMILTON	Number of Families 001

Coverage Description and Limits of Liability						
Section I Coverages	_	Limit	Se	ction II Coverages	1	_imit
A. DwellingB. Other StructuresC. Personal PropertyD. Loss of Use	\$	95,000 9,500 66,500 19,000	F.	Personal Liability Medical Payments to Others	\$	Each Occurrence Each Person
Section I Deductible	_	500	Per Occurrence	·		

Premium Summary (This is not a billing)		Activity
BASIC POLICY PREMIUM	555.00	NEW POLICY
TDTAL ADDITIONAL PREMIUM	110.00	
TOTAL POLICY PREMIUM	665.00	
CREDITS: PAYMENT RECEIVED	665.00	
ACCDUNT NUMBER: AAAW251205		

HO 7001 01 95






Metropolitan Sewer District of Greater Cincinnati **Wastewater Collection Division Project Tracking Form**

Project No. <u>00682-08</u>	Priority: 1 Enter Date: 01/31/2008		
Complaint Tracking Information			
Date: Address: No Complaint Avail	able		
Address: 1252 ROSS AV	Project Classification		
	MSD Project		
Intersection:			
ROSS AV & MAYFIELD AV	Main Line New Installation Manhole New Installation		
Mun_twnshp CINC Sub_area EPRICE	Main Line Replacement Manhole Replacement Manhole Repair Manhole Repair		
Location	Main Line Bulk Head Manhole Rehabilitation		
ALREADY LOCATED AND MARKED, SEE TAP LOCATION	Main Line Fill, Seal and Abandon		
SHEET.	Force Main Replacement Manhole Raise		
	Force Main Repair Encasement Installation		
Manhole From: 25005011	Force Main Valve Replacement Encasement Repair Force Main Valve Repair Cleanout Installed		
Manhole To: 25012027	Low Pressure Force Main Replacement Low Pressure Force Main Repair		
Condition Reported (Max of 50 Char.)	Low Pressure Force Main Valve Replacement		
WIB: BROKEN DOWN IN R/W.	Low Pressure Force Main Valve Repair Building Lateral New Installation Building Lateral Replacement		
Charge_to:	☐ Building Lateral Repair ☐ Building Lateral Relocate Other		
Contractor:			
Sub Contractor:	Start: 01/31/2008 Finish: 02/04/2008		
Contract No. / Cost Center:	Estimated Days to Complete: 3.0		
Project	Cut Size: Length 6 Width 4		
/Supervisor: PHIL WEIMER	Number Of Cuts: 1 Avg_depth 8.0		
Project Inspector:	Street Opening Permit: T200800553		
Crew Leader/	Utilities:		
Foreman: NATE POWERS	Water Works:		
OVERALL PROJECT DIFFICULTY: DIFFICULT	(Easy, Moderate, Difficult)		
last Day was not worken	y For. Futin tap on the east 18t. tap is located		

Page 1

Project No. 00682-08

Restoration			Street Openin g Permit	#: T20080	0553
Material	Туре	Address		Qty	Unit
ASPHALT	PAVEMENT	1252 ROSS AV,	CINCINNATI	48	.S.F.
CONCRETE	SIDEWALK	1252 ROSS AV,	CINCINNATI	48	S.F.






Enter Date: 01/31/2008

Comments

EMERG. TAP REPAIR, WIB, TV CREW LOCATED BLOCKAGE IN R-O-W. THE TAP RUNS FROM 1252 ROSS AV INTO MH 25012027. UPON EXCAVTION TV UP AND DNSTM ON TAP FOR CONDITION IN R-O-W. THE LATERAL BYPASSES A 12" SEWER THAT RUNS FROM 25012024-25012023. IT MAY BE POSSIBLE TO TIE INTO THE 12" SEWER LINE AND FSA THE DS SECTION OF THE LATERAL, IF THIS OPTION IS CHOSEN MAKE NOTE THAT THE 12" SEWER IS LINED.Crew replaced 19' of 6" h/tand installed 2-way c/o

Printed on 04/03/2008 Submit By: RANDY Submit Date:01/31/2008



INFORMATION FOR REQUEST FOR REVIEW

Name:	MARIO HARRIS AND VICTORIA PATMAN
Address:	1252 ROSS AUE
	Cincinnati Ohio 45205
Phone:	513-240-6908 513-498-3766
Nature of di	spute and description of your disagreement (attach additional pages if necessary):
Row_	SEWAGE WAS COMING UP IN MY BASEM
my c	I'S AGREEMENT IS WHY dON'T THAY WO
to how	ENER THERE Claim when the problem
WASE	VI ON MY PROPERTY IT WAS IN THE
middle	E of the STREET. SO how GAN IT GE
ON ME	and my faithly my PRODERTY Ends AT
the Di	NK THE BRAKS WAS IN THE GREEN.
7	
Date of City	's decision (please attach): MARCh 28, 2008
Please attack	Relief that you are seeking and any evidence that you have to support your claim. h your original claim and other documents (receipts, photos, videos, etc.) that you he Court to review:
Check one:	
	I would like to appear in person to explain my position to the Court.
	I do not need to appear in person. I would like the Court to issue a decision based on its review of this form and the attached documents.
Signature:	Maris Harris
Date:	4-20-08

^{**} File this form and any relevant documents at the Clerk of Court's office in Room 103 of the Federal Courthouse, 100 E. 5th Street, Cincinnati, OH 45202; and send a copy to the City of Cincinnati, c/o Terry Nestor, 801 Plum St., Room 214, Cincinnati, OH 45202, and/or Fax: *513-352-1515*.

Filed 05/14/2008 Page 7 of 25

estessor of the 122

Value City Furniture

VALUE CITY FURNITURE 4293 WINSTON AVENUE COVINGTON, KY 41015 (859)491-1300

DATE 2/04/2008 TIME 12:42:48

Li 1/

149.99

FS0

650381

-01

USTOMER: (H) 513-244-1007 VICKY MARIO PATMAN 1252 ROSS AVE Customer: CINCINNATI, OH 45205

> Furniture NAMES OF THE PARTY AND THE PARTY.

Pickup..:

ORD SHP PRICE TOTAL QTY QTY FSO FSO FSO FSO FSO FSO FSO

1001779 1 ITEM #: 2753-105 1. 1001779 ET STAND-HERITAGE HILL

2 800562 2 149.99 299.98 ITEM #: VC900AC-334 SGL LEANING BKCASE-A&C NATL Limited Lifetime Warranty

449.97 Merchandise Total. KY KED7 Sates Tax 0 6.000% 27.00
Invoice Hotal

PRICE QUOTE WATDERDE TURES
This IS NOT a Soles Receipt No Payment has been Received

CUSTOMER COPY



BIG BOB'S - COVINGTON 3819-21 WINSTON AVE COVINGTON, KY

Telephone: 859-261-8000 Fax: 859-655-6572

Page 1

ES800479

QUOTE

PATMAN, VICTORIA AND MARIO 1252 ROSS CINTI, 45205

02/04/08

513-24**4-**1007

ES800479

Inventory Style/Item Color/Description Quantity Units Price Extension

JAMBOREE FAWN 936.00 SF 1.00 936.00

- 02/04/08		— 12:23PM —
Sales Representative(s):	Material:	936.00
JASON FLYNN	Service:	0.00
	Misc. Charges:	0.00
This is an estimate only. Sizes/Qty to be confirmed by customer or by	Sales Tax:	56.16
customer's installer.	Misc. Tax:	0.00
WE ARE ONLY RESPONSIBLE FOR LABOR PURCHASED THROUGH BIG BOB'S.	QUOTE TOTAL:	\$992.16
		**

Long's Wholesale Furniture

8451 Vine Street Cincinnati, Ohio 45216 513-631-3555 6537 Dixie Highway Fairfield, Ohio 45014 513-942-5550

Estimate For	
Mattress Series#	
Bunk Bed Model#	
With Reg Matts	(Complete)
With Innerspring Matts	(Complete)
Living Room Sets: Model#	•
Sofa/Loveseat set	
ChairCoffee and End Table sets: Models	
D=:	
Lamps: Model#	
Price per lamp	
X	
Dinettes: Model#	
Price	
	31 \$440
Bedroom sets: Model# B338-	/ /
Price includes Oresser Mirror, Hea	adboard
And Frame	
Chest	
Nightstand	
Misc.	
DELIVERY COMPANY IS NOT EMP	
SUBCONTRACTED FROM THE COM	IPANY. DELIVERY WILL BE

AN ADDITIONAL FEE. LONGS DOES NOT ASSEMBLE.

DELIVERY COST IS APPROXIMATELY 170

PIER 1 IMPORTO, 6027 8083 MONTBOMBEY ROAD OMONIATI, ORIO 1994

Papasan Chair Frame 2118057 Papasan Honey Chair Cushion 2170081

2 × Cushion @ 60.00 = $\frac{120.00}{28.00}$ 2 × Frame @ 69.00 = $\frac{138.00}{258.00}$ Plus Tax $\frac{16.77}{6.590}$ # $\frac{274.77}{700}$ TOTAL WARRING TROPA

TOTAL CHARGES OF ALL MERCHANDISE & SERVICES

STOCK MERCHANDISE TO BE PICKED UP:

CUSTOMER PICKUP

REF# R01

397-676

1.00

C X E

SOLD TO

City



CINCINNATI, OH 45213 Store 3832 PLEASANT RIDGE 3400 HIGHLAND AVE

> Phone: (513) 631-1705 Salesperson: JBP4WH

> > Page 1 of 2 No. 3832-211286

Reviewer:

HARRIS Address 1252 ROSS AVE CINCINNATI 오 45205 MARIO & VICTORIA Company Name Job Description DEHUMIDIFIER HAMILTON (513) 244-1007 2008-02-04 14:28 Prices Valid Thru: 02/05/2008

MERCHANDISE AND SERVICE SUMMARY we reserve the right to limit the quantities of REF #W02 SKU #515-664 Customer Pickup / Will Call

E/O LDH65EBL 65 PINT ENRGSTR DEHUM, B/ DESCRIPTION

END OF CUSTOMER PICKUP - REF #W02

MERCHANDISE TOTAL

PRICE EACH

EXTENSION \$219.00 \$219.00

\$219.00

ORDER TOTAL **BALANCE DUE SALES TAX** TOTAL \$233.24 \$219.00 \$233.24 \$14.24

ORDER No. 3832-211286

Page 1 of 2

* 2	WICKER CHAIRS 1YR
* .	WICKER CHAIRS 1YR CARPET 3 MONTH Old IN A ROLL NEVER US
* 2	BOX FANS TURCHASED IN MAY FOR SUMMER MOUTHS
_ X 2	Shelts 6 MONTHS THAY WEAR PURCHASED
Æ	STEREO CADINET NEW NEVER USED
*	DEHUMIDIFIER PURCHASED MAY 07
* 4	DEHUMIDIFIER PURCHASED MAY 07 TEXT DOOKS PROPERTY OF C.P.S DONT NO PRICE
X	DRESSER FURCHASED MAY 07
	Toys 1 Box PurchaseO on 12-07 other Box was
	old Toys CAN'T REMEMBER WHAT IN all the Items
	WAS THE Things I PRICED WAS FROM CHRISTMAS in 07, Child is 10 yrs old. All THESE Things was purchasED AROUND the Time WE MOVED
	in or, Child is 10 yes old. All these Things
7	WAS PURCHASED AROUND THE TIME WE MOVED
	IN with which was 7 OR & months ago to
	START. FINISHENG BASEMENT FOR KIDS. CAN'T
	fine shelfs but but willing TO companise
	for the ShEHS i pricED.
	\mathcal{M}
	Mary Marys
	forty at the
	\$ \$326.314
	ESTMATED PROCE OF
	,- accumenta for destroyer
	Property,
	<u> </u>

	Dung the Charmy
	PERMISSION TO ENTER
Property Address:	· • • • • • • • • • • • • • • • • • • •
	,
Date:	
	i i
I,	, own/legally occupy ied above, which has recently experienced basement flooding.
Cincinnati ("MSD' Hamilton County, permission to enter	elow, I hereby grant to the Metropolitan Sewer District of Greater'), the City of Cincinnati, the Board of County Commissioners of their employees, contractors, agents or other representatives, upon my property at the address specified above for the following formed at MSD's expense:
	visually inspect the property and / or to perform tests to determine the se of the flooding in my basement.
floo spill	clean the floor, walls, and other surfaces affected by the basement ding. Cleaning may include wet vacuuming or other removal of lage; mopping bare floors with cleaning solution and disinfectant; ing walls with cleaning solutions and disinfectant; flushing out and

goods; and related other supporting services.

form if necessary):

To remove and dispose of any and all items of personal property which have been damaged by the flooding, except for the following items which I specifically direct shall be left in my basement (write on the back of this Hear are some copys of the complaints and the steps of had to take befor I got two the bottom of the problem then it came out to be MSD problem it wasen't on my property.

> Mario Hami col 513-240-6908 three 513-244-1007 cell 513-2498-3766

		¥£	A Second American Second Secon
			. 502-
M S D WIB PRO	PERTY	O)	FFSITE DISPOSAL REPORT
· · · · · W	B No,	ال	57
Customer Service Representative	, Kat	e	<u> </u>
Customer Name: Mario	City	7	2NC Zip: 45205
Item Description	Quantit		Comments
Chairs-wicker	\mathcal{C}		
→	200	7	Concington REASIXAG
Carpet		<u>u</u>	KM BIREA SIXOG
box fans	2		
Shelf -small			CANT find shelfs any
AL.		:	more But will
Short-large	<i>1</i>		3compromise for these
Stereo cabinet	+		70.0
e.			
huntidifier	1.	٠.	1 May 1
1 2	21000	_	,
TOYS	abaxa	<u></u>	
text beaks	4_		Moth Speling, Social Studios
dresser			7
Circsser	-		
		`	the state of the s
			-
*		_	·
**************************************	J		
4*		3	
Cleanup Contractor:			Date: <u>Q-1-08</u>
Employee Signature: Customer Signature:	Aic)	+	11/1/R1 <
Printed Name: V Man In	Jan	-	Date: X Q-1-08
By signing this report, I agree that the	items liste	d al	bove will be disposed of offsite and are eligible for
inclusion in my claim.			
	,		Povised 4/5/2006



City of Cincinnati



Office of the City Solicitor

March 28, 2008

Room 214, City Hall 801 Plum Street Cincinnati, Ohio 45202 Phone (513) 352-3334 Fax (513) 352-1515

Patricia M. King Interim City Solicitor

Victoria Patman & Mario Harris 1252 Ross Cincinnati, Ohio 45205

Re: 1252 Ross Avenue

Dear Ms. Patman & Mr. Harris:

This office is charged with reviewing damage claims related to the Metropolitan Sewer District's water in basement program. Your claim was sent to the MSD, and an investigation was conducted based on the history at 1252 Ross Avenue.

Based on the investigation, the City is denying your claim. The Metropolitan Sewer District found Condoms and Sanitary Items within the building sewer that caused the back-up. MSD determined that maintenance of the entire house/building lateral rests with the property owner. MSD will repair or reconstruct that portion of house lateral within the street right-of-way that fails due to a broken or collapsed pipe.

The responsibility of each property owner is identified clearly within the Rules and Regulations of the Metropolitan Sewer District as set forth in Section 1207 thereto. (Please See Attached.)

Sincerely, Shary & Sensy

Claims Manager

City of Cincinnati



Office of City Solicitor

2/14/2008

Room 214, City Hall 801 Plum Street Cincinnati, Ohio 45202 Phone (513) 352-3334 FAX (513) 352-1515

J. Rita McNeil City Solicitor

Victoria Patman 1252 Ross Avenue Cincinnati, Ohio 45205

Dear Mr./Ms. Patman:

This letter is to acknowledge that the City Solicitor's Office has received your claim for damages.

We are sensitive to your situation, however, as with all claims, the City of Cincinnati must conduct a full investigation.

While we are conducting our investigation, if you have not already done so, please send the following information to the Office of the City Solicitor, Attention: Claims Administrator, 801 Plum Street, Room 214, Cincinnati, Ohio 45202:

- 1. Any documentation related to the amount of your damages (receipts, estimates, bills, etc.).
- 2. A copy of your insurance coverage related to your claim.

Please be informed that pursuant to Section 2744.05(B) of the Ohio Revised Code, if the City of Cincinnati is liable for the claimed damages, it is only liable for the amount that is not covered by insurance. If you need further explanation concerning the above, please call me at 352-1577.

The Claims Administrator will notify you by mail of the decision regarding your claim at the completion of the investigation.

Sincerely yours,

Shirley Lenzly

Claims Administrator

Ş∐jr

Ref #: 8264

Page 21 of 25

Date: 01/31/08

Time: 12:00

Received: THA

COMPLAINT FORM

ALLER INFORMATION_

Wastewater Collection Division

Name: MARIO HARRIS

Agency: Private

Address:

Business Phone:

Home Phone:

240-6908

'ROBLEM LOCATION_

Address: 1252 ROSS AV

Nearest Intersection: ROSS AV & MAYFIELD AV

City/Township@INC

EAST P

Detailed Location Information: USNG 1M: GJ0984432436

Condition Reported: Water - In - Basement

Comments: Water - In - Basement

SEE ACTION COMMENTS

Current Condition: Water - In - Basement

ON SITE INSPECTION___

Date: 01/31/08

Arrival Time: 12:01

Unit Number: 422 Completion Time: 12:02

Dispatch Time: 12:00 Condition Found: No Main Sewer Trouble

Action Taken:

Comments: WIB.REFER TO J.WEIMER TO TV PER D.MADDEN. TV LAUNCH FOUND REPAIR IN ROW PER D.MADDEN

REFERRED TO ETC TO CLEAN AT15:39.REFER TO J.WEIMER FOR TV INFO. T. HAMBURG

ASSIGNED M # 01587-08 TO MLM TO TV LAUNCH HOUSE TAP. 2-1-08 TONY ROLLISON

Job Order:

Last Referral:

Last Referral Date: 02/01/08

For:

Final Disposition

Date: / / By:

Responsibility Of: Metropolitan Sewer Distri

Case 1:02-cv-00107-SAS Document 240 Filed 05/14/2008 Wastewater Collection Division

Page 22 of 25

Date: 01/29/08 Time: 15:43

COMPLAINT FORM

Received: JKN

ALLER INFORMATION_____

Name: MARIO HARRIS

Agency: Private

Business Phone:

Home Phone:

240-6908

ROBLEM LOCATION_

Address:

Address:

1252 ROSS AV

1252 ROSS AVE CINCIN

City/Township@INC

Nearest Intersection: ROSS AV & MAYFIELD AV

EAST P

Detailed Location Information: USNG 1M: GJ0984432436

Condition Reported: Water - In - Basement

Comments: Water - In - Basement

SEE ACTION COMMENTS

Current Condition: Water - In - Basement

N SITE INSPECTION____

Date: 01/29/08

Unit Number: 444

Dispatch Time: 15:48

Arrival Time: 16:05

Completion Time: 16:20

Condition Found: No Main Sewer Trouble

Action Taken:

Comments: HAD PLUMBER. PRIORS.

MSD RODDED ON 1-7-08. CHECKED USMH 25012027 (C/ IS TAPPED DIRECTLY INTO THIS MH) & DSMH 25012023. BOTH ARE OPEN & RUNNING, NMST, NBUIMHS. ADVISED C/ OF FINDINGS.J. LOSEKAMP

1-29-08

.lob Order:

Last Referral:

Last Referral Date: 01/30/08

For:

Final Disposition

By: WITHERS

Date: 01/30/08

Responsibility Of: Private

Case 1:02-cv-00107-SAS Document 240 Filed 05/14/2008 Wastewater Collection Division

Page 23 of 25

Date: 01/15/08

COMPLAINT FORM

Time: 13:51

Received: ERE

LLER INFORMATION____

Name: MARIO HARRIS

Agency: Private

Address:

1252 ROSS AVE CINCIN

Business Phone:

Home Phone:

240-6908

ROBLEM LOCATION_

1252 ROSS AV Address:

City/Township@INC

Nearest Intersection: ROSS AV & MAYFIELD AV

EAST P

Detailed Location Information: USNG 1M:GJ0984432436

Condition Reported: Water - In - Basement

Comments: Water - In - Basement SEE ACTION COMMENTS

Current Condition: Water - In - Basement

N SITE INSPECTION____

Date: 01/15/08 Unit Number: 442

Dispatch Time: 13:58 Arrival Time: 14:33 Completion Time: 14:55

Condition Found: No Main Sewer Trouble

Action Taken:

Comments: WIBNOW:Y SRC:Fldrain P:N PRIORS MSD RODDED 135' TO ML 1/7/08; TAMPONS & CONDOMES. IT

WAS STILL B/U; INTERNAL. CK ML ONLY.

CK'D 18'' U/S MH 25012023 & D/S 25012027. O&R, NO SIGNS OF B/U. NICE FLOW OF WATER IN

ML. EVERYTHING IS OK. J. ROBINSON 1/15/08

Job Order:

Last Referral: Last Referral Date: 01/16/08

For:

Final Disposition

By: WITHERS

Date: 01/16/08

Responsibility Of: Private

Case 1:02-cv-00107-SAS Document 240 Filed 05/14/2008 Page 24 of 25

Date: 01/07/08

COMPLAINT FORM

Time: 13:16

Received: ERE

ALLER INFORMATION_____

Wastewater Collection Division

Name: MARIO HARRIS

Agency: Private

Business Phone:

498-3766

Address:

1252 ROSS AVE CINCIN

Home Phone:

240-6908

PROBLEM LOCATION_

1252 ROSS AV Address:

City/Township@INC

Nearest Intersection: ROSS AV & MAYFIELD AV

EAST P

Detailed Location Information: USNG 1M:GJ0984432436

Condition Reported: Water - In - Basement

Comments: Water - In - Basement SEE ACTION COMMENTS

Current Condition: Water - In - Basement

ON SITE INSPECTION_____

Date: 01/07/08

Unit Number: 441

Dispatch Time: 16:00

Arrival Time: 16:42

Completion Time: 19:13

Condition Found: No Main Sewer Trouble

Action Taken:

Comments: WIBNow: Y SRC: Fldrain Freq: 1st P:N NO PRIOR OR PLUMBER, RUN AFTER 5PM.

CK'D 18'' ML U/S MH 25005011 & D/S 25012027 & 25012028. NSMT & NBUIMH. HAD TO CHISEL OFF BASEMENT FLOOR C/O. REPLACED W/ A 3.5'' THREADED CAP. COULDN'T GET 3.5'', 2.5'' OR NAKED CHAIN TO GO. CHISELED OFF 3.5'' BRASS CAP ON STACK C/O. REPLACED W/ A 3.5'' PLUG. RODDED 135' TO ML. COULDN'T HEAR CHAINS IN MH 425012027. HIT A ROUGH SPOT AT 105' IN ROW. NO OTHER OBSTRUCTIONS. SEWAGE IS STILL HOLDING IN F/ DRAINS IN BASEMENT. A/C THEY HAVE AN INTERNAL PROBLEM. PULLED BACK TAMPONS & CONDOMES. JOE HOMER 1/7/08

Job Order:

Last Referral:

Last Referral Date: 01/15/08

For:

Final Disposition

By: WITHERS

Date: 01/15/08

Responsibility Of: Private

Metropolitan Sewer District of Greater Cincinnati Wastewater Collection Division Project Tracking Form

Project No. 00682-08

Address: 1252 ROSS AV	MSD Project
Intersection: ROSS AV & MAYFIELD AV	Contract No. /
Mun_twnshp CINC Sub_area EPRICE	Cost Center:
Location ALREADY LOCATED AND MARKED, SEE TAP LOCA	Project Engineer: PHIL WEIMER Project
Manhole From: 25005011	Inspector:
Segment ID: 25005011-25012027	Finish: 02/04/08
Condition Reported (Max of 50 Char.)	
WIB: BROKEN DOWN IN R/W.	Cut Size: Length6
	Width 4

Comments:

EMERG. TAP REPAIR, WIB, TV CREW LOCATED BLOCKAGE IN R-O-W. THE TAP RUNS FROM 1252 ROSS AV INTO MH 25012027. UPON EXCAVTION TV UP AND DNSTM ON TAP FOR CONDITION IN R-O-W. THE LATERAL BYPASSES A 12" SEWER THAT RUNS FROM 25012024-25012023. IT MAY BE POSSIBLE TO TIE INTO THE 12" SEWER LINE AND FSA THE DS SECTION OF THE LATERAL, IF THIS OPTION IS CHOSEN MAKE NOTE THAT THE 12" SEWER IS LINED.Crew replaced 19' of 6" h/tand installed 2-way c/o

